Parts needed to mount the TAN-C5 extrusion

Extrusion (A)

End caps (B)

Cover (C)

LED strip (D)

Tools needed for mounting:

-mounting glue

**NOTE!** All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found at www.klusdesign.eu

1. Mount the LED strip (D), insert the cover (C), insert the end cap (B).

2. Feed the power cable. Spread the glue on the surface.

3. Connect power to the LED strip and attach the extrusion (A).