


Parts needed to mount the LESTO extrusion



Extrusion (A)



End cap (B)



Cover (C)



LED strip (D)



Spring (E)


Tools needed for mounting:

- springs for grooves


WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly. More methods and related accessories can be found at www.KlusDesign.eu

1. Mount the LED strip (D), insert the cover (C), insert the end cap (B).



2. Slide the springs (E) into the extrusion (A) channels.



3. Connect power and mount the extrusion (A) by bending the springs.

